

FIG. 1 A




FIG. 1 B




FIG.1C




FIG.1D




FIG.2A




FIG.2B




FIG. 2C

impossible to form by coating method




FIG. 2D






FIG.2E

lowering of cross sectional area




FIG.2F




FIG.3A




FIG.3B




FIG.3C




FIG.3D




FIG.3E




FIG.3F






FIG. 4A




FIG. 4B




FIG.4C




FIG.4D




FIG.5A




FIG.5B




FIG. 5C




FIG.5D






FIG. 5E




FIG.5F




FIG.5G




FIG.5H




FIG.5I




FIG. 6A




FIG.6B




FIG. 6C






FIG. 6D




FIG. 7A




FIG.7B





FIG. 7C






FIG.7E




FIG. 7F




FIG.8A






FIG.8B




FIG.8C




FIG.8D




FIG.8E




FIG. 8F




FIG.9A




FIG.9B




FIG.9C






FIG.9D




FIG.9E




FIG.9F




FIG.10A




FIG.10B




FIG.10C




FIG. 11




FIG.12A






FIG.12B




FIG.12C




FIG.12D :




FIG.13




FIG.14

